



005333

STATE OF COLORADO

COLORADO DEPARTMENT OF HEALTH

4210 East 11th Avenue
Denver, Colorado 80220-3716
Phone (303) 320-8333

Telefax:
(303) 322-9076 (Main Building/Denver)
(303) 320-1529 (Pitkin Place/Denver)
(303) 248-7198 (Grand Junction Regional Office)



Roy Romer
Governor

Thomas M. Vernon, M.D.
Executive Director

TO: Pat Smith

FROM: Glenn Mallory *GFM*

DATE: August 15, 1990

RE: Barter Machinery, Site Investigation Critique

Per our conversation and the above referenced, undated, critique on Barter Machinery please consider the following:

- (1) My memo dated May 21, 1990 changed the initial recommendation from an emergency clean-up. The efforts between the PRPs to come to an agreement are still ongoing. Normal CERCLA procedures for clean-up/enforcement should be followed by EPA.
- (2) Page one of the Sampling Activity Report (SAR) mentions the cooperative agreement and screening site investigation (SSI).
- (3) Page 1 of the Sampling Plan (SP) references the SOP. In addition, the Compendium of Superfund Field Operations is used for reference.
- (4) Soil samples were taken to characterize soils for possible PCB contamination (SP, page 1). Soil Samples were taken in the 0 to 12" depth range per SAR page 3. The exception to this was BM-SO-7 which was a surface grab sample per the SAR.
- (5) Organic analysis was done by
ESECO
73332 S. Alton Way, Suite H
Englewood, CO 80112
Phone #303-741-0639
As transcribed from the CLP list date 4/1/88
- (6) All analytical data was generated under CLP protocol per SP page 4.
- (7) The FIT (Field Investigation Team) performed the QA (data validation) on the analytical data only.
- (8) It is noted that the table containing the organic analysis results is missing the sample location; a corrected table is attached. All maps/diagrams mentioned in the critique were part of either the SP or SAR. Copies are with our file copies of the ARR; additional copies have been included with this memo.

*table
not
attached
- JES*

GFM/cg/7649